



Key:
 = Appears load bearing
 = Appears non-load bearing

Note:

- These findings are based on visual inspection only.
- The walls noted as non-load bearing may be providing support to secondary structure such as ceiling, services, etc.
- Load bearing nature and wall constructions to be fully confirmed on site prior to full removal of any walls.